

HLL TEMPORARY LIMITATION NOTICE

NOTICE TO: All Pilots

TLN NUMBER: 040-2025

SUBJECT: Judy Platform with Ensco 120 and Island Patriot

alongside Judy Riser

TLN ISSUED: 1 October 2025

EXPIRY DATE: 12 November 2025



PRIMARY ASSET	SECONDARY ASSET(S)
Judy	Ensco 120, Island Patriot

COMMENTS

The Ensco 120 and the Island Patriot will be alongside the Judy Riser Platform for approximately 5 months.

Ensco 120 / Island Patriot

The Island Patriot will be working alongside the Ensco 120 from the 1st Oct – 12th Nov.

Where practicable, approach and departure to be flown clear of Island Patriot. Table 1 may apply if overflight unavoidable.

When Island Patriot Position A-B: Potential 5:1 infringement or performance considerations with wind from direction 010° - 120° for landing, 170° - 300° for departure.


When Island Position C-D: Potential 5:1 infringement or performance considerations from wind direction 240° - 350° for landing, 040° - 170° for departure.


Check Helimet weather and the Ensco 120 radio for current position as per Figure 3 + 4.

Given this is a multi-helideck project, all helidecks not expecting the arrival of a helicopter shall extinguish their TD/PM & H lighting. This will assist in the mitigation of wrong deck landings. TD/PM & H lighting will be illuminated at least 30 minutes prior to the expected arrival time of a helicopter as part of the HLO helideck inspection duties. This applies at all times of day.


Aircrew are requested to submit voyage reports advising HCA if the information above is incomplete or incorrect.


02 | IMAGES / DRAWINGS





Coloured concentric circles indicate limit of crane operation. Approaches and departures to the Judy should be flown clear of the pink shaded area. This ensures at least 65m clearance from the respective cranes at their full reach.





03 | HLL LIMITATIONS

		ı	n	V
J	L	J	u	1

LIMITATION/COMMENT	WIND (T°)	SPEED (Kts)	NON-COMPLIANCES				
EXISTING LIMITATIONS							
 Platform Table 1 (T & L) if overflight of the south / east and west monitor platforms is unavoidable Prohibited Landing Heading Sector & Offset TD/PM - HLO Refuge Cleared for S92 	141° - 161°	All	 210°: Handrails at NW and S access approx. 300mm adl 150°: HLO refuge 330mm from edge of SLA and 1m adl 5:1: Perimeter net at south foam monitor platform Foam monitor platform east and west side various deck structures below helideck west side Miscellaneous: NDB Unserviceable 				
ADDITIONAL LIMITATIONS							
 Fig 2 - EN120 Cranes - Cranes may be operating on EN120 during helicopter operations to the Judy. Approaches or departures to/from Judy to remain clear of sector 303° – 003° due to crane activity on the EN120. Fig 2 - Judy Cranes – NOT PERMITTED during helicopter operations to the Judy. 	303° – 003°		Nil.				

ENSCO 120

LIMITATION/COMMENT	WIND (T°)	SPEED (Kts)	NON-COMPLIANCES				
EXISTING LIMITATIONS							
 Jack up No flights while under tow Helideck net fitted to achieve required friction standards Dual Agent not fitted (Norway) No Landings when net removed. Helideck being repainted, possibility of reduced markings between 15th - 25th August. 	All	≥30	210°:) Nil. 150°:) Nil 5:1:) Nil Miscellaneous:) Comprehensive electronic pitch, roll and heave measuring equipment.) Not required when jacked up				
ADDITIONAL LIMITATIONS	ADDITIONAL LIMITATIONS						
 Fig 1 - Exercise Caution due turbulence Fig 1 - Table 2 Judy Cranes – only inboard cranes to be used during helicopter operations to the EN120. Judy JRP Crane – NOT PERMITTED during helicopter operations to the EN120. EN120 Cranes – NOT PERMITTED during helicopter operations to the EN120. Fig 3 – Orange Sector – Table 1 L Fig 3 – Green Sector – Table 1 L Fig 4 – Orange Sector – Table 1 L Fig 4 – Green Sector – Table 1 T 	130°-190° 130°-190° 010°-120° 170°-300° 240°-350° 040°-170°	20-30 >30	Nil.				

HCA-FRM-009 Rev 02 - 7 - March 2025